



Photo 5-Looking northwest from near southeast corner of Parcel 1. Note shed to far left and cycle building distant center. Area in foreground contains piles of horse manure.



Photo 6-Looking southwest at Property from near the northeast corner of Parcel 1 at Hwy PD and Country View Road.



Photo 7-Looking southeast at the southern portion of Parcels 3 and 4.



Photo 8-Looking east along northern Property line from near midpoint of Parcel 2. Note horse shed in photo center and barn and horse arena in distance.



Photo 9-Looking at southeast corner of cycle shop. Note small diameter pipe in photo center which appears to be a drain pipe from a sink located in the southeast corner of the building (see Photo 10).



Photo 10-Looking at sink in southeastern corner of cycle building. Note drain pipe extends through wall and exits as noted in Photo 9.



Photo 11-Looking at former waste oil drum storage area inside cycle building. Note some limited staining of concrete.




Photo 12-Looking at indoor horse arena located on southern portion of the barn building.